


# Help Me Find Parts



Dear Half-Mast,

We're having to order new IM-93 dosimeters because the protective caps or pocket clips disappear. Surely there is some way to replace caps and clips besides ordering new IM-93s at around \$60 a pop.

SGT R.R.

Dear Sergeant R.R.,

There surely is. Order a new clip with NSN 5340-01-369-3311. You can make a new cap with tape or aluminum foil like it says on Page 3-8 in TM 11-6665-214-10.

Half-Mast

M41 PATS...

## YOU DON'T NEED SWABS

**NBC** NCOs, you don't need swabs to clean the storage cap and alcohol cartridge for the M41 protection assessment test system.

The NSN for the swabs listed in TM 3-4240-349-12&P is no longer good and SBCCOM discovered replacement swabs are too expensive. So once you use up your supply of swabs, use the lint-free cloths that come with PATS for cleaning the cap and cartridge. They work just as well as the swabs.

This changes the procedure on Pages 0016 00-1 and -2 in the -12&P. Make a note.

